

## Bureau of Home Furnishings and Thermal Insulation

### Modified Language

Changes to the originally proposed regulation are shown in *Italics* with double underline for new text and ~~strikeout~~ for deleted text.

**Adopt section 1383.7 of Title 4 of the California Code of Regulations to read as follows:**

#### **1383.7. Compliance Fee Rate Schedule.**

The Bureau may require a licensee who was inspected and found not in compliance with any one or more of the Bureau's regulations to pay fees to cover the costs of inspections and the laboratory testing necessary to investigate and enforce compliance. These fees shall be fixed as follows:

##### (a) Laboratory Fees:

1. Component Testing on component samples received separately from finished products such as, but not limited to, polyurethane foam pad, upholstery fabric, plumage, blended cotton batting, synthetic fiber batting, and loose fills, etc.

\$200.00 for each component.

2. Finished Completed Articles such as, but not limited to, upholstered chairs, upholstered sofas, pillows, mattresses, mattress box spring sets, futons, and thermal insulation products, etc.

\$300.00- Technical Bulletin 106

\$300.00- Technical Bulletin 116

\$500.00- Technical Bulletin 133

\$500.00- Technical Bulletin 603

\$500.00- Technical Bulletin 117

\$500.00- Insulation Test

3. Inspections

\$200.00- Labeling

\$500.00- Sanitization

##### (b) Inspection Fees (No Laboratory Testing Involved):

\$200.00 for the first identified element of non-compliance

\$50.00 for each additional element

\$500.00 maximum for any one inspection

Note: Authority cited: Sections 19034 and 19213, Business and Professions Code.

Reference: Sections 19170 and 19213.1, Business and Professions Code.